

## Rear Support Table Conversion




table from the Mark V, before preforming conversion.

## NOTE

The reference numbers in these instructions, refer back to the original parts explosion from the instructions (845211) received with the support table.

- 1. Remove Hex head cap screw (4) from bracket, also remove the lock washer (5). Save these. This will remove the old brackets and tube.
- 2. Insert the lock washer (5) and the Hex head cap screw (4) through each hole in the new bracket. Tighten all four screws

Discard the left old parts, they will no longer be used.

**NOTE** 

3. To mount your rear support table to the worktable slide your connector tube through one bracket, through the table extrusion, and through the other bracket.

## **NOTE**

If you should need further assistance, please call our Customer Service Department Toll-Free 800/762-7555 or visit our website www.shopsmith.com.

Shopsmith, Inc. The Premier Woodworking Company 6530 Poe Avenue Davotn. Ohio 45414

845495 Rev 5/01 Printed In U.S.A.